

Introduction to AC Machines

- ◆ Introduction
- ◆ Sinusoidally-distributed Windings
- ◆ Air gap field distribution
- ◆ Three-phase windings
- ◆ Space vectors to represent sinusoidal distributions

Introduction


- Primary AC motor drives

 - ◆ Induction motors



 - ◆ Permanent Magnet Brushless (Synchronous Motors)

Both have similar stators but different rotor construction

- Stator windings produce sinusoidal field distribution



Sinusoidally-distributed Stator Windings



Conductor density $n_s(\theta) = \hat{n}_s \sin(\theta)$ [no. of conductors / rad] $0 < \theta < \pi$

Total

$$N_s = \int_0^\pi n_s(\theta) d\theta = \int_0^\pi \hat{n}_s \sin(\theta) d\theta = 2\hat{n}_s$$

$$\Rightarrow n_s(\theta) = \frac{N_s}{2} \sin(\theta) \quad 0 < \theta < \pi$$

Air-gap Field Distribution

$$H_a(\theta) = -H_a(\theta + \pi)$$

$$H_a(\theta)l_g - H_a(\theta + \pi)l_g = 2H_a(\theta)l_g$$

(negative sign because line of integration points inwards at $\theta + \pi$)

$$2H_a(\theta)l_g = \int_0^\pi n_s(\theta + \xi) i_a d\xi$$

$$2H_a(\theta)l_g = \frac{N_s}{2} i_a \int_0^\pi \sin(\theta + \xi) d\xi = N_s i_a \cos(\theta)$$



$$\Rightarrow H_a(\theta) = \frac{N_s}{2l_g} i_a \cos(\theta)$$

$$H_a(\theta) = \frac{N_s}{2l_g} i_a \cos(\theta)$$



$$B_a(\theta) = \mu_o H_a(\theta) = \left(\frac{\mu_o N_s}{2l_g} \right) i_a \cos(\theta)$$

$$F_a(\theta) = l_g H_a(\theta) = \frac{N_s}{2} i_a \cos(\theta)$$

Field quantities have different magnitudes and units but same shape



Three-phase sinusoidally-distributed stator windings



□ Example



$$B_a(\theta) = \frac{\mu_o N_s i_a}{2l_g} \cos \theta = 0.628 \cos \theta \text{ Wb/m}^2$$

$$B_b(\theta) = -0.440 \times \cos(\theta - 120^\circ) \text{ Wb/m}^2$$


$$B_c(\theta) = -0.188 \times \cos(\theta - 240^\circ) \text{ Wb/m}^2$$

$$B_s(\theta) = B_a(\theta) + B_b(\theta) + B_c(\theta) = 0.967 \cos(\theta - 13.03^\circ)$$

Space Vector to Represent Sinusoidal Distributions



- Properties of sine(cosine)
 - ◆ sum of two sine = sine
 - ◆ integral/derivative of sine = sine
- Complex number representation



$$F_a(\theta, t) = \frac{N_s}{2} i_a(t) \cos(\theta) \Leftrightarrow \vec{F}_a(t) = \frac{N_s}{2} i_a(t) \angle 0^\circ$$

Similarly, $\vec{F}_b(t) = \frac{N_s}{2} i_b(t) \angle 120^\circ$ $\vec{F}_c(t) = \frac{N_s}{2} i_c(t) \angle 240^\circ$

And $\vec{F}_s = \vec{F}_a + \vec{F}_b + \vec{F}_c = \hat{F}_s \angle \theta_{F_s}$

- Similar expressions for B and H


Example

Three-phase, sinusoidally-distributed stator with $\frac{N_s}{2} = 50$ turns
At time t , $i_a = 10A$, $i_b = -10A$ and $i_c = 0A$


Find \vec{F}

$$\begin{aligned}\vec{F}(t) &= \frac{N_s}{2} (i_a \angle 0^\circ + i_b \angle 120^\circ + i_c \angle 240^\circ) \\ &= 50 \{ 10 + (-10) [\cos 120^\circ + j \sin 120^\circ] + (0) [\cos 240^\circ + j \sin 240^\circ] \}\end{aligned}$$

$$\vec{F}(t) = 50 \times 17.32 \angle -30^\circ = 866 \angle -30^\circ \text{ A} \cdot \text{turns}$$



at t



If $l_g = 1.5 \text{ mm}$ and $\mu_m = \infty$, find $\vec{B}(t)$.

$$\vec{B}(t) = 0.73 \angle -30^\circ \text{ T}$$

Summary

Introduction to AC Machines

- ◆ Sinusoidally-distributed Windings
- ◆ Air gap field distribution
- ◆ Three-phase windings
- ◆ Space vectors to represent sinusoidal distributions